


# City of Afton Natural Resource Inventory Water Resource Evaluation



**Washington Soil and Water Conservation District**  
In cooperation with  
**Lower St. Croix Valley Watershed District**

# Afton Natural Resource Inventory Water Resources Evaluation

## Table of Contents

Introduction

1. Natural Resource Inventory Criteria.....	1
1.1 General Information.....	1
1.2 Landscape Units Criteria.....	1
1.3 Water Quality Management Criteria.....	1
1.4 Groundwater Recharge/Infiltration/Permeability Criteria.....	2
1.5 Erosion Index Criteria.....	2
1.6 Natural Resource Inventory Criteria - Water Resource Features.....	3
2. Valley Creek Watershed.....	8
2.1 Location and General Description.....	9
2.2 Landscape Units.....	9
2.3 Water Quality Management Goals.....	9
2.4 Groundwater Recharge/Infiltration/Permeability.....	10
2.5 Erosion Index Ranking.....	11
2.6 Natural Resource Inventory Results.....	11
3. Rest Area Pond Subwatershed.....	15
3.1 Location and General Description.....	15
3.2 Landscape Units.....	15
3.3 Water Quantity Management Goals.....	15
3.4 Groundwater Recharge/Infiltration/Permeability.....	16
3.5 Erosion Index Ranking.....	16
4. Fahlstrom Pond Subwatershed.....	17
4.1 Location and General Description.....	17
4.2 Landscape Units.....	18
4.3 Water Quality Management Goals.....	18
4.4 Groundwater Recharge/Infiltration/Permeability.....	18
4.5 Erosion Index Ranking.....	18
5. Lake Edith Subwatershed.....	19
5.1 Location, General Description and Drainage Patterns.....	19
5.2 Landscape Units.....	19
5.3 Water Quality Management Goals.....	19
5.4 Groundwater Recharge/Infiltration/Permeability.....	20
5.5 Erosion Index Ranking.....	20
6. Bailey Lake Subwatershed.....	21
6.1 Location, General Description and Drainage Patterns.....	21
6.2 Landscape Units.....	21
6.3 Water Quality Management Goals.....	21
6.4 Groundwater Recharge/Infiltration/Permeability.....	21
6.5 Erosion Index Ranking.....	21

7. Kelles Coulee Subwatershed.....	22
7.1 Location, General Description and Drainage Patterns .....	22
7.2 Landscape Units .....	22
7.3 Water Quality Management Goals.....	22
7.4 Groundwater Recharge/Infiltration/Permeability.....	23
7.5 Erosion Index Ranking.....	23
7.6 Natural Resource Inventory Results.....	23
8. Swede Hill Subwatershed.....	26
8.1 Location, General Description and Drainage Patterns .....	26
8.2 Landscape Units .....	26
8.3 Water Quality Management Goals.....	26
8.4 Groundwater Recharge/Infiltration/Permeability.....	26
8.5 Erosion Index Ranking.....	26
9. Trout Brook Subwatershed.....	27
9.1 Location, General Description and Drainage Patterns .....	27
9.2 Landscape Units .....	27
9.3 Water Quality Management Goals.....	27
9.4 Groundwater Recharge/Infiltration/Permeability.....	28
9.5 Erosion Index Ranking.....	28
9.6 Natural Resource Inventory Results.....	28

### **List of Tables**

Table 1	Watersheds of Afton with Drainage Area
Table 2	Erosivity Index Ranking and Values by Subwatershed
Table 3	Water Resources Rankings by Watershed
Table 4	Combined NRI Results – Water Resources Evaluation
Table 5	Water Resource Recommendations

### **List of Figures**

Figure 1	Subwatersheds in Afton
Figure 2	Subwatershed Water Quality Rankings
Figure 3	City of Afton Groundwater Recharge/Total Infiltration Potential Rankings
Figure 4	City of Afton Soil Hydrologic Groups
Figure 5	City of Afton Surficial Geology Permiability
Figure 6a-6i	Erosivity Index Rankings
Figure 7	City of Afton Natural Resource Inventory – Water Resources
Figure 7a1-7a9	Valley Creek Subwatershed Water Resources NRI
Figure 7b1-7b7	Kelles Coulee Subwatershed Water Resources NRI
Figure 7c –7c7	Trout Brook Subwatershed Water Resources NRI

### **List of Appendices**

Appendix A	Water Management and Quality Information
------------	--